SPARX 3 PHASE POWER BOX

SIMPLY CONNECT THE 3 OUTPUT WIRES FROM THE 3 PHASE STATOR TO THE 3 YELLOW AC WIRES OF YOUR SPARX BOX. THE RED+ AND THE BLACK- THEN CONNECT INTO YOUR MOTORCYCLE WIRING

BRITISH CYCLE SUPPLY Call (902)542-7478 Fax (902)542-7479 info@britevele.com

